

Prepared by & Retur	n to: Herold - Reicks Surveying, 10	East Man Str	eet, New Hampton, IA 90659, Ph. 64-394-2725
U	nited States Public Lar	•	
Section 21, Towns	Land Survey M hip 96 North, Range 11 West o On file in Document #2020-0	f the Fifth Pri	ncipal Meridian, Chickasaw County, Iowa.
This certificate is being prepared in compliance ☐ There with Iowa Code Chapter 355.11 because: ☐ There ☑ There ☑ There			is no certificate on file for this corner. are no longer three valid ties of record. are changes to reference ties of record. is change of monumentation of record. Ify description of record monument (ties).
Monument Descr	iption and Remarks:		
	Set 1"Ø Bronze Survey Marker PLS Corner obtained prior to highway re		
	Pla	n View	The state of the s
Show a minimum of three r	- -		nd physical conditions that will enable recovery of the corner.)
e e	50.65' Fd. 1/2"Ø Rebar 1'± North of Wood Corner Post #	County Read VS6 (Union Avenue)	
		er of Section 2	
		Survey Marker P	
KIRK D. REICKS 19211	I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed Land Surveyor under the laws of the State of Iowa. Kirk D. Reicks Date: License number 19211		List Corner to be Indexed Corner Section Twp. Range E 1/4 21 96 11
W. W. W. W.	My license renewal date is December 31, 2020. Sheets covered by this seal: Individual sheet only		Project Number: 2019-810 FB: 2019 Construction, Pgs. 14-36
		Jinase oraj	10, 2015 Constitution, Pgs, 14-50

Instrument #: 2020-0265 02/18/2020 01:17:58 PM Total Pages: 1 SCC SECTION CORNER CERTIFICATES Recording Fee: \$ 7.00 Shirley Treyna, Recorder, Chickasau County Iowa

Prepared by & Return to: Herold - Reicks Surveying, 10 East Main Street, New Hampton, 14 50659, Ph. 641-394-2729 United States Public Land Survey Corner Certificate Land Survey Monument situated in Section 21, Township 96 North, Range 11 West of the Fifth Principal Meridian, Chickasaw County, Iowa. Not on file in the County Recorder's office. ∑ There is no certificate on file for this corner. There are no longer three valid ties of record. This certificate is being prepared in compliance There are changes to reference ties of record. with Iowa Code Chapter 355.11 because: There is change of monumentation of record. To clarify description of record monument (ties). **Monument Description and Remarks:** East 1/4 Corner: Found PK Nail with information obtained from the County Engineer's Office, in Section Tles Book, Township 96, Range 11. **Plan View** (Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.) Sec. 21 T96N **R11W** 21 Projects - NHO\County Control Systems - NHO\CHICKASAW\CHICK-23\CHICK-23-2020.dwg, 2/13/2020 3:57:38 75.55 Fd. 1/2"Ø Rebar (2 Typ.) 65.90 50.65 Field Entrance Fd. 1/2"Ø Rebar 1'± North of Wood Comer Post 1/4 Section Line 50.00 Set 5/8"Ø Rebar with Orange Plastic Cap PLS 19211 at the Intersection of ROW and 1/4 Section Lines

East 1/4 Corner of Section 21-96-11

Found PK Nail

I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed Land Surveyor under the laws of the State of Iowa.

Kit D. Kito 2-14-2020 Kirk D. Reicks Date:

My license renewal date is December 31, 2020. Sheets covered by this seal: Individual sheet only List Corner to be Indexed


Cor C-21-96-11

Corner Section Twp. Range € 1/4 96 11

> Project Number: 2020-009 F8: Chickasaw 10, Pgs. 10-12

اي

COUNTY ENGINEER'S SECTION CORNER PRESERVATION RECORD



MONUMENT DESCRIPTION AND NARRATIVE Found PK noil in HMA mat

From Chickasaw County Project plans found Pl is 0.6' west of center line. Information was also found in the county engineer tie book.

All ties are GPS surveyed.

I AM NOT A REGISTERED LAND SURVEYOR UNDER THE LAWS OF THE STATE OF IOWA

JIM FOSTER CHICKASAW CO. DATE: 07/23/10