Section 30-90-11
As referred to in
Engl. The Book

TeKIPPE ENGINEERING, P.C., 128 South Vine Street, We	st Union, Iowa	52175	Phone (319)	422-5131
UNITED STATES PUBLIC LAND SU	JRVEY CO	RNER C	ERTIFIC	CATE
OF				
Land Survey Monuments situated in Section	an, <u>CH</u>	ICKASAW	C	ounty, Iowa.
Previously recorded in	iber, etc.)	_ in Cour	ity Recor	der's Office.
(Show reason for preparing this certificate, the evidence the corner positions and monumentation found or placed.		rocedures	ısed in est	ablishing
Monument Description and Remarks: W 1/4 Corner Section 29 T96N R11W: Set 1/2" ø rebar				
w/2"ø aluminum cap PLS 15525 at the interse	ection of the	Section	Line fen	ce with
the 1/4 Section Line fence.				
SW Corner Section 29 T96N R11W: Set 1/2" ore	bar w/2"ø a	luminum	cap PLS	15525 by
doubling the distance from the W 1/4 Corner,				
SW Cor. NW 1/4-NW 1/4, Section 32.				
PLAN (Show a minimum of three reference ties to durable phy conditions that will enable recovery of the corner.)		elevant mo	FF	oject Number 00271.IS n. 46H PG, 45-49 nd physical
Set orange plastic tag plast 15525 tag PLS 15525 North side wood fence post 12.70' Corner of 2' angle iron corner post W 1/4 Corner Section 29 T96N R11W Set 1/2"\$\psi\$ rebar \(w/2\)"\$\psi\$ aluminum cap PLS 15525	1	ange tag 525 5ide pole	N R11W	Utica Twp. Utica Twp. Cor. B 30-96-// cop PLS 15525
was prepared and the related survey work was performed by me or under my direct personal	Corners	Section	Twp.	Range
supervision and that I am a duly licensed land Surveyor under the laws of the State of Iowa.	W 1/4	29	96N	11W

SW

Paul R. Herald 04-02-01

My license renewal date is December 31, 2002. Sheets covered by this seal: Individual

Paul R. Herold License number 15525 29

County Enginees

11W

96N