
Sec. 19-94-14 As ref. to in Engr Tie Brok



Monument Description. Remarks, and Plan View:

NE Cor. NW% NE% - History of Corner =

1998,Feb — 1999, May 21 —

1999, May 21 -

Fig. Hinge Noil' per lowa DOT District 2 Office Field Book Page 6. 'Fd. Hinge Noil' per Co Rec's Book 171 Page 456. 'Found hinge noil' per Co Rec's Book 171 Page 460. 'Fd. Hinge Noil' per Co Rec's Doc. #2000—1801. 'FOUND HINGE NAIL' per Co Rec's Doc. #2000—2207. 'Found hinge noil' per Co Rec's Doc. #2001—2853 2000, Aug. 28 -2000, Oct. 31 -

Found hinge noil per Co Rec's Doc. #2001-0853. Found Hinge Noil per Co Rec's Doc. #2003-1869. 2001, May 01 -2001, Oct. 31 -

2008, Oct. 16 - 'Fd. Hinge Noil' per Co Rec's Doc. #2009-0297.


Previous and current Co Engr's ties do not indicate type of monumentation with ties as shown above.

Searched area with a metal detector, excavated 0.4' x 0.3' deep hole at magnetic reading. Found an iron concrete nail, 0.2' deep, tied out and removed nail as this monument does not match record. Continued excavating to 0.5' deep and found a ½" p iron pin, 0.4' deep in apparent centerline of traveled surface of ACC road North-South and in-line with fenceline remnants East. Location of monument found matches that of record and one remaining record tie is within reason. Therefore, used pin as the correct corner. All ties are plumb distance.

Note: Noil was S02'22'55"W, 0.09' from that of pin.

This certificate is being prepared because there are no longer three valid ties of record and there is a change to monumentation of record.

SE Cor. SW14 NE14



Monument Description, Remarks, and Plan View:

SE Cor. SW% NE% - History of Comer =

SE Cor. SW/x Ne. - History of Corner = 1999, May 21 — 'Set Mag-Noil W/Stainless Steel Washer' per Co Rec's Book 171 Page 456.

1999, May 21 — 'Set Mag-Noil W/Stainless steel washer LS7060' per Co Rec's Book 171 Page 462.

2001, Oct. 18 — 'Set Mag-Noil W/Stainless Steel Washer LS 7060' per Co Rec's Doc. #2003-1869.

2008, Oct. 16 — 'Fd. Mag-Noil W/Stainless Steel Washer LS 7060' per Co. Rec's Doc. #2009-0297.

2008, Dec. 22 — Preliminary Plat of Smith's Country Acres Addition Indicates usage of corner, but not type of monumentation.

Previous Co Engr's ties indicate that corner was monumented with 'IRON PIN'.

Current Co Engr's ties indicate that corner is monumented with 'set Mag-Nail w/washer #7060'.

Comer Recovery =

Visually searched area and found a MAG nail with washer stamped 'LS 7060 L TEKIPPE' flush in apparent centerline of traveled surface of ACC road North—South and in—line with fenceline East. Location of monument found matches that of record, monument found matches that of record and record ties are within reason. Therefore, used noil as the correct corner. All ties are plumb

This certificate is being prepared because there are no longer three valid ties of record.

Legend

BC = Noil with Bottle Cop
BP = Brace Post
CP = Corner Post
CMP = Cornyagted Metal Pipe
CM = 4" Sq Concrete Monument with
1/2" & kon rerod in center (tie to rerod)
CX = Cut 'Y'

CX = Cut 'X'
GP = Gate Post


ID = Inside Diameter
CD = Cutside Diameter
PP = Power Pole
PW = No3! with Plastic Washer
RCP = Rehiforced Concrete Pipe
RH = Red Head (No3! in wire)
RCW = Right of Way
RW = No3! with Reflective Round Washer

R/W == Iron ROW Roll
SFP = Steel 'T' Post
SW = Noll with Square Metol Washer
TP = Telephone Pedestal
TW == Noll with Round Metol Washer
WFP == Wood Fence Post
X == X Nolls

Pg 3 of 4

P:\808\CHICKASAWCO\\$309414\SMITH4851\dwg \4851Corcert.dwg

TEKIPPE ENGINEERING, P.C., 128 South Vine Street, West Union, Iowa 52175 Phone (319) 422-5131 UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE 94 North, Range Land Survey Monuments situated in Section , Township CHICKASAW _ County, Iowa. __West, of the Fifth Principal Meridian, in County Recorder's Office. none Previously recorded in _ (book, page, document number, etc.) (Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.) Monument Description and Remarks: SW Corner SE 1/4-NE 1/4 Section 30 T94N R14W: Set MAG nail w/stainless steel washer IS 7060 at the intersection of the quarter-quarter section line and the extension of the quarter section line fence. E 1/4 Corner Section 30 T94N R14W: Set 1/2"ø rebar w/2"ø aluminum cap IS 7060 by doubling the distance from the Center of the Section to and across the SW Corner SE 1/4-NE 1/4 of Section 30. PLAN - VIEW (Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.) Sec. 30 T94N





I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I em a duly licensed land Surveyor under the laws of the State of Iowa.

Set MAG nail w/stainless steel washer LS 7060

Julie G. Tellippe Date
License number 7060
My license renewal date is December St, 2000.

Corners	List Corners Section	to be Indexed Twp.	Range
SW-SE-N	E 30	94N	14W
Corn	oc ai	30-94-14	
E 1/4	30	94N	14W
Con	· · ·	31-94-14	

Set 1/2*ø rebor w/2*ø aluminum cap LS 7060

My license renewal date is December St, 200 Sheets covered by this seal: Individual

Ylaced in Tie Bork / 99 County- Engineer's Copy 5/99