

Prepared by: <u>Kyle A. Johnson</u> Address: <u>1900 ME</u>	DICAL ARTS AVE S. SUITE 100 SARTELL, MN Phone: 1-888-937-5150
UNITED STATES PUBLIC	LAND SURVEY CORNER CERTIFICATE FOR
Land survey monuments situated in Section	. Township 96 NORTH
Range 12 WEST	_ , of the Fifth Principal Meridian,CHICKASAWCounty, lowa.
Previously Recorded in	in County Recorder's Office.
(Show reason for preparing this certificate, the evidence and detailed procedures used i	n establishing the corner positions and manumentation found or placed.)
MONUMENT DESCRIPTION AND REMARKS:	
WEST QUARTER: Westwood Professional Services found a 1/2" location and set 3 ties. Filing corner location as there are no longer	rebar 0.6' deep near N/S road centerline and fence line west. Accepting corner ger 3 valid ties of record.
SOUTH QUARTER: Westwood Professional Services found a 1/2 south. Accepting corner location as best available evidence. Filing	2" square bar 0.2' deep 7' south of centerline that agrees with field lines north and g corner record as there is no certificate on file for this corner.
	PLAN - VIEW
(Show a minimum of three reference ties to durable physical objects, relevant monur	nents and physical conditions that will enable recovery of the corner.)
N.T.S.	10
SOUTH QUARTER FOUND "X" NAILS IN FENCE CORNER Q SET 3/8IN REBAR WITH CAP SET 60D NAIL IN TOP OF FENCE CORNER	SET MAG NAIL IN EAST FACE OF WOOD POST

Cor. A 10-96-12



Corners to be Indexed			
Section	Тwp.	Range	
10	96	12	
10	96	12	
	Section 10	Section Twp.	