2002 OCT 22 AM 9 18

CIMDY MESSERSMITH COUNTY RECORDER

| | 1 77 7 7 50175 | Phone (563) 42 | 22_5131 |
|---|-----------------------------------|------------------------|---------------------------|
| TEKIPPE ENGINEERING, P.C., 128 South Vine Street, We | | | |
| UNITED STATES PUBLIC LAND S | URVEY CORNER | CERTIFICA | ΓE |
| OF | | | |
| Land Survey Monuments situated in Section _ | 29 Township | 96 Nor | th, Range |
| Land Survey mondments studied in become _ | | | nty, Iowa. |
| 12 West of the Fifth Principal Merid | | unty Recorde | - |
| Previously recorded in | nber. stc.) | unty Recorde. | is office. |
| (Show reason for preparing this certificate, the evidence | | used in establi | shing |
| the corner positions and monumentation found or placed | i.) | | - |
| Monument Description and Remarks: Center of | Section 29 TORN F | H2W: Found 3 | 3" x 9" |
| Monument Description and Remarks: Center of | from the Chickens | w County En | gineer's |
| x 15" granite stone with information obtained | Grath Tree Discod | out_V on et | one. Set |
| Office in Field Book Corner Ties, Jacksonville | Odi North of stone | Cut A OII B | .0110. 200 |
| 1/2"ø rebar w/2"ø aluminum cap PLS 15525, | U.ZI NOTTH OF STORE | ning 717/1"d a | luminum os |
| SE Corner NW 1/4 - SW 1/4 Section 29 T96N | Rizw: Found 5/6 0 | pipe w/I v a | on recorder |
| 2886 with information obtained from a Surve | y and Plat made b | y L P. Erdin | Bras 274 |
| in the Chickasaw County Recorder's Office Jan | nuary 23, 1981 in D | | |
| PLAN - | VIEW | Project Nur FB. 46J | nber 02239.LS PG 41-42 |
| (Show a minimum of three reference ties to durable ph | | | |
| conditions that will enable recovery of the corner.) | yuluur oojoon, rere | | |
| | | 900 20 | -⊥aa+- |
| | | Sec. 29 T96N | |
| <u> </u> | | R12W | |
| | | | ^ - +- |
| | | <u>L</u> | |
| | | South Jack: | sonville Twp. |
| 1 | | | |
| | | | |
| | | | |
| Set 1/2's rebor ed West of steel post | | | |
| No. | | | |
| 31103 1111 110 100 | Set 1/2"¢ rebor North of steel | | . Set 1/2"ø re |
| Set 1/2" o rebar w/2" o cluminum | fence post 23.21 | | North of ste |
| cop PLS 15525 0.21' North of stone | | / | |
| Set 1/2" prebor South of brace post | -45- | 1,63 | |
| 300 til 51 51000 \$000 | | Set 1/2*¢ | |
| <i>₹</i> | | rebar | |
| Set orange plastic tag PLS 15525 | | | |
| top of wood gate post | | | |
| | | | |
| i cor. O | | | |
| 1.7 | Cor. I | | |
| , , , , , , , , , , , , , , , , , , , | | | |
| Center of Section 29 T96N R12W Found 3" x 9" granite stone. Placed cut—X on stone. | | | |
| Set 1/2"ø rebar w/2"ø aluminum cap PLS 15525, | SE Corner NW 1/4 - SW | | |
| 0.21' North of stone | Found 5/8"ø pipe w, | /) p aluminum co | p 2886 |
| | | | |
| I hereby certify that this land surveying documen | 1t | rs to be Indexed | _ |
| was prepared and the related survey work was performed by me or under my direct personal | Corners Section | а Тупр. | Range |
| supervision and that I am a duly licensed Land Surveyor under the laws of the State of Iowa. | Center 29 | 96N | 12W |
| Y PAUL R. 121 | 25 | 00.1 | |
| HEROLD S POUR HELDED 10-18-00 | _ | | |
| Paul R Herold Date | SE-NW-SW 29 | 96N | 12W |
| License number 15525 My license renewal date is December 31, 2002. | Filed | 11-5-02 | |
| Cheste served by this seek Individual | - | | |

Sheets covered by this seal: Individual

X:\Section Corners\Sec. 29\29-96-12mq.dwg

! County Engineus
Copy 11