Section 13-94-13
As referred to in
Engr. Tie Book

SLSI 9-90
UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE
OF /3
And Survey Monuments situated in Section 24, Township 94N, Range 1.3 W, of the Fifth Principal Meridian, CHICKASAW County, Iowa. Previously recorded in (None) in County Recorder's Office. Show reason for responding this certificate, the available part decided procedures used in actabilishing the corresponding and Township.
(book, page, document number, etc.) Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monu- nentation found or placed.) Monument Description and Remarks: Found IRON PIPE WITH IDOT ALUMINUM
CAP 14" DEEP, RAISED WITH YZ"O REBAR WITH CAP,
PLAN - VIEW Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable ecovery of the corner.)
FOUND X-NAILS IN 30" O OAK

ROAD EAST EDGE OF UNDERGROUND CABLE" STEEL SIGN POST

Cor A 13-94-13

N/4 CORNER SECTION Z4-T94N-RI3W

I hereby certify that the survey work was completed and this certificate was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of lowa.	List Corners to be Indexed Corners Section Twp Range N/4 2.4 94N 1.3 W
Signature G. Ochgui Nume typed or printed: Lyle G. TeKippe	
Date: 4-10-92 Reg. No. 7060	
THER. & LAND	\mathcal{C}
SEAL LYLE G. TEKIPPE 7080	Placed in the Book,
Maria	