	TATES PUBLIC LAN	ID SURVEY CORNE	R CERTIFICATE	
Land Survey Monuments situated in	Section 15	, Township	96 N	, Range
, of the I	Fifth Principal Meridian, _	Chickasa	w	County, lowa.
Previously recorded in	N/A		in County	Recorder's Office.
Monument Description and R Reason for preparing certificate: Continuous Conti	orner certificate for East	1/4 Corner of Section 15 i osition: Corner position o	s not on file. established, see below.	
Monumentation found or placed:	East 1/4 Corner - Sour	•		
(Show a minimum of three reference  East 1/4 Corner Section 15-96-11 Fd. 1/2" rebar 3" di	ties to durable physical objects, reli	Entrance Drive	Staple; SEC 15 R 11 V	N 96 L
I hereby certify that the survey we and this land surveying documen me or under my direct personal si I am a duly licensed land surveyor the State of Iowa.  Signature:	t was prepared by upervision and that r under the laws of RD, P.E. & L.S.		List Corners to be Index Section Tw 15 96	


(1/c # s	DOCUMENT RECORDING TRANSFER F	No00839	FILED FOR RECORD THE	17thbay or , 19. 96, at 8:52 2. Deedspage 202	STATE OF IOWA, CHICKASAW, COUN  REITHA N. R.  By	DSS Depoty	
Prepared by: Erdman Engineering P.C. 708 Commerce Drive, P.O. Box 246, Decorah lowa, 52101 Phone (319)382-4194, Fax (319)382-3623							
		United States Public Land Survey Corner Certificate					
		of					

Land Survey Monuments situated in Section. \*\* Township. 96 Range, 11 of the Fifth Principle Meridian, Chickasaw County, Iowa. Previously recorded in Book 162 p.58 in County Recorders Office.

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)

Monument Description and Remarks: This certificate is prepared in accordance with Section 355.11 of the 1995 Code of lowa. No previous certificate has been filed for this corner location. Based on County Engineer's Reference Ties we found a 1" bar, two sets of "X" nails one 1/2" bar all used as tie markers. From these ties we found a 1/2" bar at the surface of the crushed rock surface at the W 1/4 corner of Sec. 14-96-11.

Plan-View (Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)



I hereby certify that the survey work was completed and this certificate was prepared by me or under by direct supervision and that I am a duly registered land surveyor under the laws of the State of lowo. Corners Section W 1/4

Lindsay Erdmon, P.E. and L.S. 14/96 Reg. Na.

My license will be renewed \_\_lanuary 1, 1997

List Corners to be Indexed Twp. Range 96 11

moor6129 8-30-95

BOOK PAGE 202