

U	nited States Public Land	Survey Corner Certificate
Section 18, Towns	Land Survey Monu Ship 96 North, Range 11 West of the Not on file in the Cour	ne Fifth Principal Meridlan, Chickasaw County, Iowa.
	peing prepared in compliance napter 355.11 because:	 ☑ There is no certificate on file for this corner. ☐ There are no longer three valid ties of record. ☐ There are changes to reference ties of record. ☐ There is change of monumentation of record. ☐ To clarify description of record monument (ties).
Monument Desc	ription and Remarks:	
	n: Found 3/4"Ø Pipe 30" Deep with infor i/th Aluminum Cap PLS 19211 overtop t	ormation obtained from the County Engineer's Office. to perpetuate the monument.
	Plan \	View
ow a minimum of three r		monuments and physical conditions that will enable recovery of the corner.
ON ON		Sec. 18 T96N R11W
	j.	
of Control	47.09' Set 5/8'0 Rebar 3' East of Guy Wire Anchor	33.00' Set 5/8'Ø Rebar with Orange Plastic Cap PLS 19211 at the Intersection of ROW and 1/4 Section Lines
RGH	ROW	WON
Ridgeway.	ave.	33.00° Set 5/8"Ø Rebar with Orange Plastic Cap PLS 19211 at the Intersection of ROW and 1/4 Section Lines 1/4 Section Line
	X	30
	Field Entrance 72.76' Set 5/8' Rebar 1'± North of Mall Box	Field Entrance Cot. 0-18-96-11
		ection 18-96-11 ebar with Aluminum Cap PLS 19211 overtop
	I hereby certify that this land surveying do	
TOWN LAND	was prepared and the related survey work performed by me or under my direct person supervision and that I am a duly licensed in	k was Corner Section Twp. Range sonal
KIRK D. 2 REICKS T	Surveyor under the laws of the State of Io	
19211	Kirk D. Reicks Da	ate:
N. C.	License number 19211 My license renewal date is December 31, 2	
WILLIAM STATE	Sheets covered by this seal: Individual she	neet only FB: Chickasaw 9, Pgs. 51-52

Project Number: 2019-064 FB: Chickasaw 9, Pgs. 51-52